

SALES ORDER

NO. 1072

DATE 4/24.86

CUSTOMER'S NO.

5 meter

TO

SHIP TO

~~WEST 10TH STREET~~ ^{SUIT 100}

SAME

SALESPERSON

DATE REQUIRED

SHIP VIA

F.O.B.

TERMS

SIGRID

S.A.P.

SMITH/TR

G-FORCE

PAID

ORDERED

DESCRIPTION

PRICE

PER

AMOUNT

1

2

12441

EXTRUSION MAST

291.00

3

EXTRA DRILLING

20.00

4

5

2/98301

PIVOT CHIP

@ 1.25

2.50

6

~~WIRE COVER~~

7

313.50

8

I had to get a new mast after a storm flipped my cat
and the mast was bent.

9

10

11

FREIGHT

53.13

12

13

14

15

16

17

18

19

20

ALLEN WE WERE UNABLE
TO DRILL YOUR MAST. REASON
BEING WE ARE UNSURE ON Hardware
ON YOUR MAST NOW. There has
been changes in the hardware over
the years. Going by your old
mast you should have no problem
drilling the extrusion yourself.
Thanks

BUYER

TOTAL

366.63